

---

# THE PROBLEM SOLVERS

---

June 2003

## AG4 4Spd. VW

On four speed 096/01M, 097/01N, 098/01L series transmissions, there is a plastic cap holding the pressure regulator valve in place.

A common problem is the small legs breaking off (*refer to ATRA Bulletin 717*) During a V/B service; these caps are not available from Volkswagen.

Precision International has added a replacement cap (*PI# 40300*) to the following kits:

|         |             |
|---------|-------------|
| 095/096 | K40900 B/X  |
| 01M     | K40900 L/BX |
| 097     | K40900 D/X  |
| 01N     | K40900 G/X  |
| 098     | K40900 H/X  |
| 01P/099 | K40900 K/HX |

Our replacement cap 40300 can be found in Sub-K40300.



Telephone #: (631) 567-2000 ☆ Fax #: (631) 567-2640  
email us: [sales@transmissionkits.com](mailto:sales@transmissionkits.com)

**PRECISION**  
**INTERNATIONAL**