

REF: Production Change #1570
TRANS: E40D,4R100
DATE: January 22, 2001

Overdrive friction plate PI# 36406 for light & medium duty applications has a waffle pattern grooved into friction material. Ford has released a Technical Service Bulletin which denotes that a ticking noise is evident in many E40D & 4R100 units. They correct this noise by replacing # 36406 with # 36111, which has a smooth surface.