

REF: Production Change #2817

TRANS: 42RLE

FOUND IN KIT:

DATE: January 30, 2009

AFFECTED KITS: K61900-4, KP61900A, KP61900AX and all related Master & Banner kits

The 42RLE requires the same Solenoid Block Connector seal as the 45RFE. We will now add 1pc. 13589 to above kits.