

REF: Production Change #3017

FOUND IN KIT:

TRANS: RE0F09A

DATE: October 12, 2010

AFFECTED KITS: K73900R-MD, K73900RX-MD and all related Master and Banner kits.

Teflon rings are required to repair the primary and secondary pulley drums for the RE0F09A. we now have the Teflon rings available and will add 2 pcs. 73866 to above kits.