

REF: Production Change #3019
FOUND IN KIT: Immediately
TRANS: U340, U341E/F
DATE: October 12, 2010
AFFECTED KITS: K7500J, K7500JT, K7500JW/O, K7500JTW/O, K7500JX, K7500JTX, K7500JXW/O,
K7500JTXW/O

As per Michael's trip report from Singapore, many Asian U340 Toyota's require 4 pcs. of 2nd brake Friction and Steel. We will add 1 pc. 75704 (Friction) and 1 pc. (75705 (Steel) to above kits to total 4 pcs. each to cover these models.