

REF: Production Change #3376
FOUND IN KIT: Immediately (D/C 15111)
TRANS: MPS6 (DCT450), SPS6 (DCT470)
DATE: April 16, 2015
AFFECTED KITS: K10900, K10900A and all related Master and Banner kits

We now have available the Front sealing covers for both above transmissions. It is recommended they be replaced on each rebuild.

1 pc. 10510 added to K10900 (Via K10900-99)
1 pc. 10525 added to K10900A (Via K10900A-99)