

REF: Production Change #3389
FOUND IN KIT Immediately (D/C 15177)

TRANS: 42RLE

DATE: June 25, 2015

AFFECTED KITS: KP61900A, KP61900AX and all related Master and Banner kits

The Output Shaft Retainer clip often breaks and is not reusable upon rebuild. We will now add 1pc. Output Shaft Retainer clip 61916 to above kits.