



PRECISION[™]
INTERNATIONAL

PRESENTS

TECH TIPS TO HELP YOU AT THE SHOP BENCH

the problem solvers

4R70W, 4R75E/W POOR OR NO OVERDRIVE

When there is an overdrive problem with a unit, it is worth looking to see if the Overdrive Servo Pin Retainer “E” Clip is broken because it can cause this problem. When the clip is broken it causes the servo piston to free itself from the pin, this results in poor or no overdrive. A replacement clip is currently in our kits PI# 37163 available in bulk, but is also included in KP37900H.



Precision International is a worldwide supplier of quality products for import and domestic automatic transmissions. As well as supplying an extensive aftermarket customer base, we also provide product to Original Equipment Manufacturers. Precision International is dedicated to providing the most up-to-date information available in the industry today.