



July 2009



K69900B

&

All Related Master & Banner Kits

Precision International is pleased to announce the availability of separate gaskets for the Valve Body separator plates in 7/98 and up vehicles. These gaskets are normally bonded to the separator plate by OEM Subaru. The following gaskets have been added:

| Description | <u>Qty</u> . | Date | Part Number |
|-------------------------|--------------|---------|-------------|
| Gasket, Main VB (Upper) | 1 | 7/98-01 | 69886 |
| Gasket, Main VB (Upper) | 1 | 02-08 | 69441 |
| Gasket, Main VB (Lower) | 1 | 7/98-01 | 69886 |
| Gasket, Main VB (Lower) | 1 | 02-08 | 69442 |
| Gasket, Aux VB (Upper) | 1 | 7/98-01 | 69884 |
| Gasket, Aux VB (Upper) | 1 | 02-08 | 69443 |
| Gasket, Aux VB (Lower) | 1 | 7/98-01 | 69885 |
| Gasket, Aux VB (Lower) | 1 | 02-08 | 69444 |

We are also replacing the original style Pump Stator Teflon rings with late style peek rings per latest Subaru updates by removing 4 pieces of 69100 and adding 4 pieces of 69555.

Please contact your PI Sales Rep or Distributor for more information

