



THE PROBLEM SOLVERS

TOYOTA U SERIES VALVE BODY GASKETS


IS 1012
AUGUST 2008




75431
OE# 35431-21010
U140E/F 1998-02,
U240E 1999-01,
U241E 2000-04,
U150E 2001, U151E/F 2003-04
VB COVER
Kits K75900ET
K75900KT, K75900E
K75900F, K75900K, K75900KT
K75900EX, K75900ETX




75075
OE# N/A
U150E 2001, U151E/F 2003-04
AUXILIARY VB (Small)
Kits K75900KT
K75900EX, K75900ETX
K75900K




75076
OE# N/A
U150E 2001, U151E/F 2003-04
AUXILIARY VB (Large)
Kits K75900KT
K75900EX, K75900K
K75900ETX




75357
OE# 35477-52020
U340/341E/F 1999-03
VB COVER
Kits K75900JTX
K75900JT, K75900JX
K75900J



75358
OE# 35488-52010
U340/341E/F 1999-03
VB COVER
Kits K75900JTX
K75900JT, K75900JX
K75900J



75122
OE# N/A
U441E 1999-05
MAIN VB (lower)
Kits K75900L



75123
OE# N/A
U441E 1999-05
VB (upper)
Kits K75900L

PRECISIONTM
INTERNATIONAL

COPYRIGHT©2006 PRECISION INTERNATIONAL. ALL RIGHTS RESERVED. REPRINTING IN WHOLE OR IN PART WITHOUT THE EXPRESS PERMISSION OF PRECISION INTERNATIONAL IS PROHIBITED