

REF: Production Change #1677
TRANS: A604
DATE: October 11, 2001

We have now added two pieces of 31006 to our K31900-6 Solenoid Repair Kit. Unlike the early solenoid which uses two seals, the late ones uses a Silicone bead around the perimeter of the plastic block for sealing. Unfortunately, it is nearly impossible to re-install this Silicone and "*squeezing in*" fresh Silicone is an imperfect and sometimes messy job at rebuild-- 31006 eliminates this problem.