

REF: Production Change # 2183

TRANS: A604

FOUND IN KIT: Immediately

DATE: January 10, 2005

AFFECTED KITS: K31900-6

We now have available Solenoid Isolater PI# 31849, and have added it to the above kit. This Isolater is a formed rubber "protector" that supports the 4 internal solenoids in the block. It is a good idea to replace it at each solenoid rebuild as contaminated transmission fluid make have begun to deteriorate the original one.