

REF: Production Change #2302

TRANS: RL4/RE4F02A/V

FOUND IN KIT: As of D/C 05293

DATE: October 19, 2005

AFFECTED KITS: K63900E, K63900M and all related Master and Banner kits

4 Cooler Line Washers (PI# 45899) are required for above units. Presently only having 1 pc., we are adding 3 pcs. 45899 for correct coverage.