

REF: Production Change #2493

TRANS: 48RE

FOUND IN KIT: As of D/C 06325

DATE: November 21, 2006

AFFECTED KITS: KP22950R, KP22950R-MD, KP2200R, KP2200RW/O

We have added OEM style Direct (Front) Clutch Inner Lip seal since many of the late drums are more closely toleranced at the factory (PI# 13310).