

REF: Production Change #2582

TRANS: O1J (CVT)

FOUND IN KIT: Immediately

DATE: May 30, 2007

AFFECTED KITS: K4000R, K4000R-1F, K4000RW/O, K4000RX, K4000RXW/O, K4000R-1S

Per info from Europe, late Audi's (2005-up) require 7 pcs. each of all Frictions and Steels. Our quantities will increase as such:

		<u>Qty Was</u>	<u>Qty Now</u>
Forward Friction	40334	6	7
Forward Steel	40435	5	7
Reverse Friction	40186	6	7
Reverse Steel	40438	6	7