

REF: Production Change #2907
TRANS: E4OD, 4R100
FOUND IN KIT: As of D/C 09329
DATE: November 24, 2009
AFFECTED KITS: KP36900G, KP36900GRX, KP36900R, KP36900RX and all related Master, Banner and Super kits

We have now depleted stock on the OEM thin Upper Valve Body gaskets (36155, 1996-E97 and 36255, L97-04). We will now replace these with .015" thick versions 36165 and 36265, respectively. Due to transmission case warpage, most technical services recommend the thicker gaskets to overcome a potential cross-leak-problem.