

REF: Production Change #3148

FOUND IN KIT:

TRANS: 01J

DATE: July 23, 2012

AFFECTED KITS: K40900R, K40900RX and all related Master and Banner kits

In order to update coverage of our 01J kits, we are adding the following components:

1 pc.	77830	Oring, Suction Pump Jet to Case
1 pc.	48321	Oring, Oil Tube Screen to Case
1 pc.	40062	Oring, Secondary Pulley Shaft
1 pc.	40021*	Oil Feed Pipe, Forward Clutch

*This should be replaced at each rebuild as the two ends of the tube ends have a tendency to wear and not seal properly.