

REF: Production Change #3470
FOUND IN KIT: Immediately (D/C 16095)
TRANS: RE4F03B
DATE: April 1, 2016
AFFECTED KITS: K63900K-MD, K63900KX-MD and all related Master and Banner kits

In order to cover through 2015, we will add

- 1 pcs. 63701LXD Gasket, Oil Pan 2012-15
- 3 pcs. 63442 Torlon ring, Bearing Ret to FWD-Overrun Drum 2009-15
- 1 pc. 63601 Oring, Servo Retainer 2012-15
- 1 pc. 63561 D-Ring, Servo Piston-SM 2012-15
- 1 pc. 63121 D-Ring, Servo Piston-LG 2012-15
- 1 pc. 38112 Oring, Speed Sensor 2012-15
- 1 pc. 45625P Oring, Solenoid 2012-15 (makes 3 pcs.)
- 1 pc. 63760 Check Ball, Valve Body (makes 3 pcs.) 2012-15