



**PRECISION**<sup>™</sup>  
INTERNATIONAL

PRESENTS

TECH TIPS TO HELP YOU AT THE SHOP BENCH

*the problem solvers*

## 45RFE, 5-4RFE, 68RFE DISTORTED ACCUMULATOR PLATE COVER

The Accumulator Plate Cover and Screws commonly need replacing as the heads of the screws located over the Accumulator piston commonly shear off and the piston will work its way out of its bore, distorting the cover. A greater durability can be achieved by using the new plate which is made of a hardened steel and the screws which are carbon heat treated. These improved screws and plate can be found in SUB-K1308. (1 PC. 13633 Cover, 7 PC. 13352 Screw)



**Precision International** is a worldwide supplier of quality products for import and domestic automatic transmissions. As well as supplying an extensive aftermarket customer base, we also provide product to Original Equipment Manufacturers. Precision International is dedicated to providing the most up-to-date information available in the industry today.