

REF: Production Change #2512

TRANS: 48RE

FOUND IN KIT: As of D/C 06347

DATE: December 12, 2006

AFFECTED KITS: KP22950R, KP2200R, KP2200RW/O

We now can update coverage on our 48RE kits to cover through 2006. We have added the following components:

1 PC. 31123 Oring, Speed Sensor

1 PC\* 22827-SP Metal Ring, Kickdown Servo Piston & Guide

1 PC. 12956 M/C seal, Adapter HSG. (4WD)

1 PC\*\* 22924 Lip seal, Front Clutch Outer (Viton)

2 PCS. 38119 Oring, Wiring Harness

\*This will make 2 pcs.

\*\* This replaces Poly Lip seal (13309) in 48RE applications