

REF: Production Change #2767

TRANS: 45RFE

FOUND IN KIT: Immediately

DATE: October 9, 2008

AFFECTED KITS: K13900-2, NK13900-CER, NK13900X-CER and all related Master & Banner kits

We have now added 6 pcs. 56994 for the Solenoid snouts on the 6 solenoids in the pack.