

REF: Production Change #3247
FOUND IN KIT: Immediately (D/C 13344)
TRANS: U340E/F, U341F
DATE: December 6, 2013
AFFECTED KITS: K75900J, K75900JX, K75900JT, K75900JTX and all related Master, Banner & Farpak kits.

We are now adding 1 pc. 89401 for the Electrical Harness Connector.