



PRECISION[™]
INTERNATIONAL

PRESENTS

TECH TIPS TO HELP YOU AT THE SHOP BENCH

the problem solvers

CD4E CRACKED DIRECT CLUTCH THRUST WASHER

Since the Direct Clutch Drum to Direct Shell Thrust Washer is under extreme duress and has a tendency to crack after many miles on the vehicle, it is recommended to be replaced at each rebuild. Therefore Precision International wanted to make these washers more available, so a new washer is included in our kits, PI # 70116.



Precision International is a worldwide supplier of quality products for import and domestic automatic transmissions. As well as supplying an extensive aftermarket customer base, we also provide product to Original Equipment Manufacturers. Precision International is dedicated to providing the most up-to-date information available in the industry today.